



Understanding Experimental Error: A Practical Guide

In experimental science, understanding and managing error is fundamental to producing reliable and accurate results. This presentation provides a practical overview of the types of errors encountered in laboratory settings and strategies for their mitigation.

The Fundamental Types of Experimental Error

Random (Indeterminate) Error

Affects precision, causing deviations in both directions. While it cannot be eliminated, it can be reduced through the use of more precise equipment and meticulous techniques.

Systematic (Determinate) Error

Affects accuracy, causing consistent deviation in one direction (readings consistently too high or too low). This type of error can often be identified and eliminated.

Gross Errors

These are easily recognised as they involve a major breakdown in the analytical process, such as spilt samples or incorrect reagent dilutions. They are typically detectable by performing sufficient replicate measurements.




Dissecting Systematic Error: Key Sources

Instrument Errors

Arise from uncalibrated or improperly maintained equipment, from volumetric flasks to electronic spectrometers. Regular calibration is essential.

Personal Errors

Stem from human factors, such as misreading an instrument or going past the equivalence point in a titration. These are often due to human oversight or technique.



Method Errors

Introduced when the underlying assumptions about the relationship between the signal and the analyte are invalid or when the experimental procedure itself is flawed.

Sampling Errors

Occur when the method of sample collection does not yield a representative sample of the material being analysed, leading to skewed results.

Understanding these distinct sources allows for targeted approaches to minimise their impact on experimental outcomes.

Systematic Error: Constant vs. Proportional



Constant Systematic Error

This error type has a fixed magnitude regardless of the sample size or analyte concentration. For example, an uncalibrated burette might consistently add an extra 0.05 mL, which becomes less significant for larger volume measurements.

Minimising instrumental errors is crucial here, through frequent recalibration and diligent equipment maintenance.



Proportional Systematic Error

The magnitude of this error is directly proportional to the size of the measurement. For instance, a 2% impurity in a sample will introduce an error that is 2% of the measured value, making it equally significant across all measurement scales.

Method errors are often the most challenging to minimise, as they involve complex interactions and may require in-depth validation to uncover the "true" value.

Mitigating Error: Strategies for Enhanced Data Quality



Instrumental Accuracy

Ensure all equipment, from glassware to advanced analytical instruments, undergoes frequent and rigorous calibration and maintenance. This directly counters instrumental errors.



Personal Proficiency

Minimise human error through careful technique, adherence to protocols, and self-discipline. Training and regular practice are key to improving individual measurement consistency.



Methodological Review

Thoroughly evaluate and validate experimental methods. This is often the most difficult area, as it requires challenging assumptions and rigorous testing to ensure the method accurately reflects the phenomenon being studied.

By focusing on these areas, researchers can significantly improve the reliability and trustworthiness of their experimental data.



Precision vs. Accuracy: Defining Data Quality

Precision

Describes how closely individual measurements agree with each other. It reflects the reproducibility of your method and how carefully the measurements were taken.

- **Repeatability:** Precision under identical conditions (same analyst, day, equipment).
- **Reproducibility:** Precision under varied conditions (different days or analysts).

Accuracy

Refers to how close a measured value is to the true or accepted value. A highly accurate measurement is free from systematic errors.

Accuracy is achieved when both random and systematic errors are minimised, ensuring the measured value reflects the true value as closely as possible.

Visualising Precision and Accuracy

Consider these visual analogies to grasp the difference between precision and accuracy:

Low Accuracy, Low Precision

Measurements are far from the target and not close to each other.

High Precision, Low Accuracy

Measurements are close to each other, but consistently miss the true value.

High Accuracy, High Precision

Measurements are close to the true value and also close to each other.

The Impact of Error on Experimental Outcomes

Understanding the nuances of random and systematic errors is vital because each type impacts experimental data differently:

- **Random Error:** While unavoidable, its presence increases the spread of your data, making it harder to discern true effects. It primarily affects the **precision** of your results. Good experimental design and repeated measurements can help average out random fluctuations.
- **Systematic Error:** This type of error shifts all your measurements in a consistent direction, directly impacting the **accuracy** of your findings. If undetected, systematic errors can lead to incorrect conclusions, even if your measurements are highly precise.

📌 Always aim for both high precision and high accuracy to ensure your experimental data is both reliable and valid.





Key Takeaways: Mastering Error in the Lab



Differentiate Error Types

Recognise random, systematic, and gross errors to apply appropriate corrective actions.



Implement Mitigation Strategies

Regular calibration, meticulous technique, and rigorous method validation are crucial.



Strive for Both Precision and Accuracy

Understand that both are essential for credible and reproducible scientific results.

By diligently addressing experimental error, we uphold the integrity of scientific inquiry and advance our understanding of the world.

Defining Accuracy: Closeness to the Truth



What is Accuracy?

Accuracy indicates how close a measurement is to its true or accepted value. It is typically expressed by the error in the measurement.

Absolute Error (E)

The absolute error, E , in the measurement of a quantity x_i is given by:

$$E = |x_i - x_t|$$

where x_t represents the true value.

Relative Error (E_r)

Often, the relative error, E_r , is a more useful quantity than the absolute error, providing a percentage deviation from the true value:

$$E_r = \frac{|x_i - x_t|}{x_t} \times 100\%$$

Accuracy measures the agreement between a result and its true value, a critical aspect of reliable experimental work.

Precision: The Reproducibility of Measurements



Definition

Precision refers to the closeness of two or more measurements to each other. It reflects the reproducibility of the measurement process, regardless of how close they are to the true value.



Key Aspect

High precision means that repeated measurements under the same conditions yield very similar results. This consistency is vital for data reliability.

While accuracy targets the bullseye, precision ensures your darts consistently land in the same spot, even if it's not the bullseye itself.



Accuracy vs. Precision: A Paracetamol Example

Consider a batch of paracetamol tablets stated to contain 500 mg of paracetamol. Four students analysed the tablets, with the true content being 100% of the stated value. Let's examine their results:

Student 1	99.5%,	99.9%	100.2%	99.4%	100.5%
Student 2	95.6%	96.1%	95.2%	95.1%	96.1%
Student 3	93.5%	98.3%	92.5%	102.5%	97.6%
Student 4	94.4%	100.2%	104.5%	97.4%	102.1%

Student 1: High Accuracy & High Precision

Their results are consistently close to 100% and to each other, indicating both accurate and precise measurements.

Student 2: Low Accuracy & High Precision

These results are tightly grouped but consistently below 100%, showing precision without accuracy.

Student 3: Low Accuracy & Low Precision

Their results are scattered and not close to the true value, demonstrating neither precision nor accuracy.

Student 4: Low Accuracy & Moderate Precision

While some values are close to 100%, the overall spread is broad, indicating moderate precision but poor accuracy.

This example highlights the importance of evaluating both accuracy and precision to fully understand the quality of experimental data.

Measures of Variation: Quantifying Data Spread

The Range

The **range** of a data set is the difference between the greatest and least values. It offers a quick, but sometimes limited, view of data spread.

Interquartile Range (IQR)

The **interquartile range** is the difference between the third and first quartiles ($Q_3 - Q_1$), providing a robust measure of variability by excluding outliers.

Variance

The **variance** measures how data points differ from the mean, quantifying the average of the squared differences from the mean.



Standard Deviation and Relative Standard Deviation

Standard Deviation (s)

Standard deviation is a key measure of how much each value in a data set varies or deviates from the mean. A small standard deviation indicates that data points are generally close to the mean.

$$s = \sqrt{\frac{\sum(x_i - \bar{x})^2}{n - 1}}$$

Relative Standard Deviation (RSD)

The relative standard deviation (*RSD*), also known as the coefficient of variation, expresses the standard deviation as a percentage of the mean, useful for comparing variability between data sets with different means.

$$RSD = \frac{s}{\bar{x}} \times 100\%$$

Example: Calculating Range and Interquartile Range

Let's find the range and interquartile range for the ages of nine members of a Community Youth Leadership Board


22, 16, 24, 17, 16, 25, 20, 19, 26.

There are (9) members of the Community Youth Leadership Board. Find the range and interquartile range of their ages:

22, 16, 24, 17, 16, 25, 20, 19, 26.

greatest value - least value = 26 - 16 Find the range.

$$= 10$$



Find the interquartile range.

$$Q_3 - Q_1 = 24.5 - 16.5 = 8$$

The range is 10 years. The interquartile range is 8 years.

Standard Deviation: An example

Find the mean and the standard deviation for the values
78.2, 90.5, 98.1, 93.7, 94.5.

$$\bar{x} = \frac{(78.2 + 90.5 + 98.1 + 93.7 + 94.5)}{5} = 91 \quad \text{Find the mean.}$$

x	$\bar{x}$	$x - \bar{x}$	$(x - \bar{x})^2$
78.2	91	-12.8	163.84
90.5	91	-0.5	.25
98.1	91	7.1	50.41
93.7	91	2.7	7.29
94.5	91	3.5	12.25

Organize the next steps in a table.

$$s = \sqrt{\frac{\Sigma(x - \bar{x})^2}{N-1}} \quad \text{Find the standard deviation.}$$

$$\sqrt{\frac{234.04}{4}} \approx 7.65$$

The mean is 91, and the standard deviation is about 7.65.

Method Validation: LOD and LOQ

Method validation **ensures** that an analytical procedure is suitable for its intended purpose. Two critical parameters are sensitivity indicators:

1

Limit of Detection (LOD)

The **LOD** is the lowest content that can be measured with reasonable statistical certainty. It represents the smallest detectable amount of an analyte, though not necessarily quantifiable.

$$LOD = \frac{3s}{\text{slope of calibration graph}}$$

Where s is the standard deviation of the response.

2

Limit of Quantitative Measurement (LOQ)

The **LOQ** is the lowest concentration of an analyte that can be determined with acceptable precision and accuracy under stated test conditions. It's crucial for reliable quantification.

$$LOQ = \frac{10s}{\text{slope of calibration graph}}$$

The LOQ is typically higher than the LOD to ensure robust measurement.

These limits are fundamental for assessing the analytical capabilities and reliability of any measurement method.